



Overview: Part of spill impact on 8" Isimiri – Imogate Pipeline Right of Way at Uzuaku. Picture was taken during Joint Investigation of 8th November 2019.



Close-up: Drilled Hole on 8" Isimiri – Imogate Pipeline at Uzuaku. Picture was taken during Joint Investigation of 8th November 2019.