



11/11/2019 13:31:11 (+1.0 hrs) Lat=5.63974 Lon=5.15268 WGS-84

Overview: Part of spill impact on 20 " Trans – Escravos Pipeline Right of Way at Ugboegungun. Picture was taken during Joint Investigation of 11th November 2019.



11/11/2019 13:53:17 (+1.0 hrs) Lat=5.64013 Lon=5.15223 WGS-84

Close-up: Illegal Fitting on 20 " Trans – Escravos at Ugboegungun. Picture was taken during Joint Investigation of 11th November 2019