




Overview: Part of spill impact on 24" Nkpoku - Bomu Pipeline Right of Way at Kpите. Picture was taken during Joint Investigation of 14th November 2019.



Close-up: Illegal Fitting on 24" Nkpoku - Bomu Pipeline at Kpите. Picture was taken during Joint Investigation of 14th November 2019.