




Overview: Part of spill impact on 28" Bomu – Bonny Pipeline Right of Way at Patrick Waterside - Bodo West . Picture was taken during Joint Investigation of 21st November 2019.



Close-up: Illegal fitting on 28" Bomu – Bonny Pipeline at Patrick Waterside - Bodo West . Picture was taken during Joint Investigation of 21st November 2019.