


**Overview:** Part of spill impact on 14" Okordia – Rumuekpe Pipeline Right of Way at Ula-Okobo. Picture was taken during Joint Investigation of 24<sup>th</sup> November 2019.



**Close-up:** Drilled Hole on 14" Okordia – Rumuekpe Pipeline at Ula-Okobo . Picture was taken during Joint Investigation of 24<sup>th</sup> November 2019.



Close-up: Drilled Hole on 14" Okordia – Rumuekpe Pipeline at Ula-Okobo . Picture was taken during Joint Investigation of 24<sup>th</sup> November 2019.