



Overview: Part of spill impact on 16'' Egbema – Assa Pipeline Right of Way at Obile. Picture was taken during Joint Investigation of 27th November 2019.



Close-up: Illegal Fitting on 16'' Egbema – Assa Pipeline at Obile. Picture was taken during Joint Investigation of 27th November 2019.