



Overview: Part of spill impact on 12'' Imo River2 – Ogale Pipeline Right of Way at Odagwa
 Picture was taken during Joint Investigation of 28th November 2019.



Close-up: Illegal fitting on 12'' Imo River2 – Ogale Pipeline at Odagwa . Picture was taken during Joint Investigation of 29th November 2019.