




Overview: Part of spill impact on 36" Nkpoku - Bomu Pipeline Right of Way at Rumuesara. Picture was taken during Joint Investigation of 30th November 2019.



Close-up: Illegal Fittings on 36" Nkpoku - Bomu Pipeline at Rumuesara. Picture was taken during Joint Investigation of 30th November 2019.



Overview: Part of spill impact on 36" Nkpoku - Bomu Pipeline Right of Way at Rumuesara. Picture was taken during Joint Investigation of 30th November 2019.