



Overview: Part of spill impact on 20 " Opukushi - Brasscreek Pipeline Right of Way at Tamogbene. Picture was taken during Joint Investigation of 21st November2019.



Close-up: Illegal Fittings on 20 " Opukushi - Brasscreek at Tamogbene. Picture was taken during Joint Investigation of 21st November2019