



Overview: Part of spill impact on on 6'' well 121T Flowline Right of Way at Youbebe. Picture was taken during Joint Investigation of 28<sup>th</sup> November 2019.



Close-up: Ruptured gas flowline on 6'' well 121T Flowline at Youbebe. Picture was taken during Joint Investigation of 6<sup>th</sup> December 2019.