




Overview: Part of spill impact on 14inch Okordia Rumuekpe Pipeline at Ikarama. Picture was taken during Joint Investigation of 28th November 2019.



Close-up: Decoated portion of pipe on 14inch Okordia Rumuekpe Pipeline at Ikarama. Picture was taken during Joint Investigation of 29th November 2019.