



Overview: Part of spill impact on 14" Okordia - Rumuekpe Pipeline Right of Way at Ikata. Picture was taken during Joint Investigation of 4<sup>th</sup> October 2019.



Close-up: Illegal fitting on 14" Okordia - Rumuekpe Pipeline at Ikata. Picture was taken during Joint Investigation of 4<sup>th</sup> October 2019.