




**Overview:** Part of spill impact on 24" Nkpoku - Bomu Pipeline Right of Way at Egbalor. Picture was taken during Joint Investigation of 11<sup>th</sup> October 2019.



**Close-up:** Illegal fitting on 24" Nkpoku - Bomu Pipeline at Egbalor. Picture was taken during Joint Investigation of 11<sup>th</sup> October 2019.