



Overview: Part of Agbada 2 well 62L Flowline at Omueke. Picture was taken during Joint Investigation of 19<sup>th</sup> October 2019..



Close-up: hacksaw cut on Agbada 2 well 62L Flowline at Omueke. Picture was taken during Joint Investigation of 19<sup>th</sup> October 2019.