


Overview: Part of spill impact on 24" Trans Escravos Pipeline Right of Way at Ogidigben. Picture was taken during Joint Investigation of 25th October 2019.



Close-up: Illegal fitting on 24" Trans Escravos Pipeline at Ogidigben. Picture was taken during Joint Investigation of 25th October 2019.