



Overview: Part of spill impact on 4" Obigbo Well 38 & 52 Flowline at Umuebulu. Picture was taken during Joint Investigation of 31st October 2019.



Close-up: Hack Saw Cut on 4" Obigbo Well 38 & 52 Flowline at Umuebulu. Picture was taken during Joint Investigation of 31st October 2019.