



Overview: Part of spill impact on 20'' Rumuekpe - Nkpoku Pipeline Right of Way at Sime. Picture was taken during Joint Investigation of 5th September 2019.



Close-up: Drilled Hole on 20'' Rumuekpe - Nkpoku Pipeline at Ibaa. Picture was taken during Joint Investigation of 5th September 2019.