




Overview: Part of spill impact on 24" Bomu - Bonny Pipeline Right of Way at Patrick Waterside_Bodo West. Picture was taken during Joint Investigation of 11th September 2019.



Close-up: Illegal fitting on 24" Bomu - Bonny Pipeline Right of Way at Patrick Waterside_Bodo West. . Picture was taken during Joint Investigation of 11th September 2019.