




Overview: Part of spill impact on 16" Egbema – Assa Pipeline Right of Way at Obile. Picture was taken during Joint Investigation of 13th September 2019.



Close-up: Leaking Illegal fitting on 16" Egbema – Assa Pipeline at Obile. Picture was taken during Joint Investigation of 13th September 2019.