




**Overview:** Part of spill impact on 14" Okordia - Rumuekpe Pipeline Right of Way at Ukpeliède. Picture was taken during Joint Investigation of 15<sup>th</sup> September 2019.



**Close-up:** Illegal fitting on 14" Okordia - Rumuekpe Pipeline at Ukpeliède. Picture was taken during Joint Investigation of 16<sup>th</sup> September 2019.