


Overview: Part of spill impact on 14" Okordia - Rumuekpe Pipeline Right of Way at Ukpeliede. Picture was taken during Joint Investigation of 14<sup>th</sup> September 2019.



Close-up: Illegal fitting on 14" Okordia - Rumuekpe Pipeline at Ukpeliede. Picture was taken during Joint Investigation of 14<sup>th</sup> September 2019.