



Overview: Part of spill impact on New 20" Kolocreek - Rumuekpe Pipeline Right of Way at Okoma1 . Picture was taken during Joint Investigation of 5<sup>th</sup> September 2019.



Close-up: Illegal fitting on New 20" Kolocreek - Rumuekpe Pipeline at Okoma1. Picture was taken during Joint Investigation of 5<sup>th</sup> September 2019.