



Latitude: 4.918478
Longitude: 7.184572
Elevation: 15.77m
Accuracy: 2.1m
Time: 09-08-2019 13:02

Overview: Part of spill impact on 12'' Imo River - Ogale Pipeline Right of Way at Okohia. Picture was taken during Joint Investigation of 8th September 2019.



Latitude: 4.91833
Longitude: 7.184626
Elevation: 14.17m
Accuracy: 2.5m
Time: 09-08-2019 14:22

Close-up: Illegal fitting on 12'' Imo River - Ogale Pipeline at Okohia. Picture was taken during Joint Investigation of 8th September 2019