



**Overview:** Part of spill impact on 4" Obelle - Ibaa Pipeline Right of Way at Ibaa. Picture was taken during Joint Investigation of 21<sup>st</sup> September 2019.



**Close-up:** Hacksaw Cut on 4" Obelle - Ibaa Pipeline at Ibaa. Picture was taken during Joint Investigation of 21<sup>st</sup> September 2019.