



Overview: Part of spill impact on 12" Oguta – Egbama Pipeline at Umunkwu. Picture was taken during Joint Investigation of 4th April 2020.



Close-up: 4" valve installed at 12 o'clock position on 12" Oguta – Egbama Pipeline at Umunkwu. Picture was taken during Joint Investigation of 4th April 2020.