



Overview: Part of spill impact on 18" Assa Rumuekpe Pipeline at Ochia-Awara. Picture was taken during Joint Investigation of 14<sup>th</sup> April 2020.



Close-up: Crude oil theft point at 12 o'clock position on 18" Assa Rumuekpe Pipeline at Ochia-Awara. Picture was taken during Joint Investigation of 14<sup>th</sup> April 2020