




Overview: Part of spill impact on 10" Diebu Creek Nun-River Pipeline at Osokama-Oporoma. Picture was taken during Joint Investigation of 15th April 2020.



Close-up: 12mm Hacksaw cut at 11 o'clock position on 10" Diebu Creek Nun-River Pipeline at Osokama-Oporoma. Picture was taken during Joint Investigation of 15th April 2020.