



Overview: Part of spill impact on 14" Okordia – Rumuekpe Pipeline at Ihunwo. Picture was taken during Joint Investigation of 17th April 2020.



Close-up: 2nos 3" weld neck flang crude theft points at 12 o'clock position on 14" Okordia – Rumuekpe Pipeline at Ihunwo. Picture was taken during Joint Investigation of 17th April 2020.



Overview: Part of spill impact on 14" Okordia – Rumuekpe Pipeline at Ihunwo. Picture was taken during Joint Investigation of 17th April 2020.



Close-up: 2nos 3" weld neck flang crude theft points at 12 o'clock position on 14" Okordia – Rumuekpe Pipeline at Ihunwo. Picture was taken during Joint Investigation of 17th April 2020.