



**Overview:** Part of spill impact on 20" Rumuekpe Nkpoku Pipeline at Ibaa. Picture was taken during Joint Investigation of 17<sup>th</sup> April 2020.



**Close-up:** 10mm drilled hole at 3 o'clock position on 20" Rumuekpe Nkpoku Pipeline at Ibaa. Picture was taken during Joint Investigation of 18<sup>th</sup> April 2020.