



Overview: Part of spill impact on 12" Adibawa Okordia Pipeline at Ikarama. Picture was taken during Joint Investigation of 25th April 2020.



Close-up: 15mm Hacksaw cut at 11 o'clock position on 12" Adibawa Okordia Pipeline at Ikarama. Picture was taken during Joint Investigation of 25th April 2020.