



Overview: Part of spill impact on 14" Okordia Rumuekpe Pipeline at Edeoha. Picture was taken during Joint Investigation of 27<sup>th</sup> April 2020.



Close-up: 3" Valve Installed at 12 o'clock position on 14" Okordia Rumuekpe Pipeline at Edeoha. Picture was taken during Joint Investigation of 27<sup>th</sup> April 2020.