



Overview: Part of spill impact on 14" Okordia Rumuekpe Pipeline at Oshika. Picture was taken during Joint Investigation of 21<sup>st</sup> April 2020.



Close-up: 3" Nipple Installed at 12 o'clock position on Picture was taken during Joint Investigation of 21<sup>st</sup> April 2020.