



Overview: Part of spill impact on 12" ImoRiver 2 – Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation 1st May 2020.



Close-up: Crude oil theft point installed at 12 o'clock position on 12" ImoRiver 2 Ogale Pipeline at Umulolo. Picture was taken during Joint Investigation 1st May 2020.