



24/04/2020 13:23:16 (+1.0 hrs) Lat=4.91561 Lon=5.61329 Alt=30ft MSL WGS-84

Overview: Part of spill impact on 16" Tunu – Brasscreek Pipeline at Agbidiama. Picture was taken during Joint Investigation of 24th April 2020.



LAT 4°54'56" N

FRIDAY 04.24.20

LONG 5°36'48" E

LOCAL TIME 11:5

Overview: Part of spill impact on 16" Tunu – Brasscreek Pipeline at Agbidiama. Picture was taken during Joint Investigation of 24th April 2020.



Close-up: Hack Saw Cut at 1 o'clock position on 16" Tunu – Brasscreek Pipeline at Agbidiana. Picture was taken during Joint Investigation of 24th April 2020.