


Overview: Part of spill impact on 8" Nkali – Imo River2 Pipeline at Odagwa. Picture was taken during Joint Investigation 21st April 2020.



Close-up: 3Nos crude oil theft points installed at 12 o'clock position on 8" Nkali – Imo River2 Pipeline at Odagwa. Picture was taken during Joint Investigation 21st April 2020.