




Overview: Part of spill impact on 12" Imo River 1- Ogale Pipeline at Etituzo-Umuololo . Picture was taken during Joint Investigation of 23rd April 2020.



Close-up: 1 1/2" Locally fabricated clamped installation with an elbow at 12 o'clock on 12" Imo River 1- Ogale Pipeline at Etituzo-Umuololo . Picture was taken during Joint Investigation of 23rd April 2020.