



Overview: Part of spill impact on 14" Okordia - Rumuekpe Pipeline at Edeoha. Picture was taken during Joint Investigation on 1st August 2020.



Close-up: 2" gate valve and 2" galvanized pipe installed at 12 o'clock position on 14" Okordia Rumuekpe Pipeline at Edeoha. Picture was taken during Joint Investigation on 1st August 2020.