



Overview: Part of spill impact on 24" Nkpoku Bomu Pipeline at Egbalor . Picture was taken during Joint Investigation 10th August 2020.



Close-up: Plugged drilled hole of 1cm diameter installed at 12 o'clock position on 24" Nkpoku Bomu Pipeline at Egbalor. Picture was taken during Joint Investigation 10th August 2020.