




Overview: Part of spill impact on 14" Okordia Rumuekpe Pipeline at Ula-lkata. Picture was taken during Joint Investigation 14th August 2020.



Close-up: 12mm smooth round-edge hole installed at 1 o'clock position on 14" Okordia Rumuekpe Pipeline at Ula-lkata. Picture was taken during Joint Investigation 14th August 2020.