



Overview: Part of spill impact on 4" Imo River2 – Imo River1 Bulcline at Igiriukwu - Isietitiuzo - Owaza. Picture was taken during Joint Investigation of 15th August 2020.



Close-up: Hack Saw Cut at 1 o'clock to 5 o'clock position on 4" Imo River2 – Imo River1 Bulcline at Igiriukwu - Isietitiuzo -Owaza. Picture was taken during Joint Investigation of 15th August 2020.