



Overview: Part of spill impact on 12" ImoRiver1 - Ogale Pipeline at Okohia. Picture was taken during Joint Investigation 17th August 2020.



Close-up: Crude theft point installed at 12 o'clock position on 12" ImoRiver1 - Ogale Pipeline at Okohia. Picture was taken during Joint Investigation 17th August 2020.