



Overview: Part of spill impact on 12" ImoRiver2- Ogale Pipeline at Igiriukwu-Isietitioha Owaza. Picture was taken during Joint Investigation on 26th August 2020.



Close-up: Hacksaw cut at 11 o'clock position on 12" ImoRiver2- Ogale Pipeline at Igiriukwu-Isietitioha Owaza. Picture was taken during Joint Investigation on 26th August 2020.