




Overview: Part of spill impact on 20" Kolocreek – Rumuekpe Pipeline at Ihunwo. Picture was taken during Joint Investigation on 24th August 2020.



Close-up: 3" Ball Valve installed at 12 o'clock position on 20" Kolocreek – Rumuekpe Pipeline at Ihunwo. Picture was taken during Joint Investigation on 24th August 2020.