



Overview: Part of spill impact on 28" Bomu – Bonny Pipeline at Owokiri.  
Picture was taken during Joint Investigation on 30th August 2020.



Close-up: 6" Crude oil theft valve installed at 12 o'clock position on 28" Bomu – Bonny Pipeline at Owokiri. Picture was taken during Joint Investigation on 30th August 2020.