



Overview: Part of spill impact on 12" ImoRiver1- Ogale Pipeline at Ogale. Picture was taken during Joint Investigation on 3rd September 2020.



Close-up: Crude oil theft point installed at 12 o'clock position on 12" ImoRiver1- Ogale Pipeline at Ogale. Picture was taken during Joint Investigation on 3rd September 2020.