



Overview: Part of spill impact on 4" Benisese well 16T Flowline at Ojobo
Picture was taken during Joint Investigation on 11th September 2020.



Close-up: Hacksaw cut on 4" Benisese well 16T Flowline at Ojobo
Picture was taken during Joint Investigation on 11th September 2020.