



Overview: Part of spill impact on 14inch okordia Rumuekpe Pipeline at Rumuekpe (Imogu). Picture was taken during Joint Investigation on 3rd December 2020.



Close-up: Plugged 3inch nipple installed at 12 o'clock position on 14inch Okordia Rumuekpe Pipeline at Rumuekpe (Imogu). Picture was taken during Joint Investigation on 3rd December 2020.