




Overview: Part of spill impact on 8'' Nkali – Imo River2 Pipeline at Odagwa. Picture was taken during Joint Investigation on 11th December 2020.



Close-up: 1 inch ball valve illegal connection and drilled hole installed at 12 o'clock position on 8'' Nkali – Imo River2 Pipeline at Odagwa. Picture was taken during Joint Investigation on 11th December 2020.