



Overview: Part of spill impact on 14" Okordia Rumuekpe Pipeine at Akinima.
Picture was taken during Joint Investigation on 30th December 2020.



Close-up: Hack Saw Cut at 12:30 o'clock position on 14" Okordia Rumuekpe Pipeine at Akinima.
Picture was taken during Joint Investigation on 30th December 2020.