




Overview: Part of spill impact on 18" Assa - Rumuekpe Pipeline Right of Way at Ochia. Picture was taken during Joint Investigation of 31st December 2020.



Close-up: 3nos of crude oil theft points installed at 12 o'clock position on 18" Assa - Rumuekpe Pipeline at Ochia. Picture was taken during Joint Investigation of 31st December 2020.